

111B Reusable Baby Bear Bath Thermometer Card

Child Bath Time Safety is a Priority!

Reusable Baby Bear Bath card with three event thermometer and custom imprint on front. Includes instructions for use on back. Start with cold water. Add hot, mixing well until the OK lights green. If no color appears the water is either too hot or too cold.


Markets:

- Hospitals
- New Parent Programs
- Day Cares
- Family Wellness Promotions

Features:

- Reusable
- Helps Prevent Tap Water Burns in the Bath

Safest temperature for bathing is 100°F.
American Burn Association



Specifications:

Overall Product Size: 2-1/8"W × 3-3/8"H × .020"

Imprint Area Size: 1-3/4"W × 1/2"H
Imprint on front.

Temperature: Cool, OK, Hot
91-94°F, 100-104°F, 113-117°F

Weight: 8 lbs./M

Pricing					
Qty./Item	250	500	1000	2500	5000
111B	\$1.69	\$1.42	\$1.15	\$.97	\$.90

Price includes a one-color imprint

5R

Other Charges					
Qty./Item	250	500	1000	2500	5000
Additional Colors/imprint	.44	.30	.23	.20	.19

Set-up/Copy Change: \$31.25v

5T

PMS Color Match Charge: \$25.00v

Production: 7-10 working days from art/order approval

FOR USING THERMOMETER:

Indicators, Cool, water and gradually green. If no indicator too cold.

- 2: Taking extreme care, thoroughly stir water to avoid potentially hot areas.
- 3: Immerse the bath thermometer completely for 15 seconds, ensuring that the water covers the black oval area of the thermometer. read the temperature of the thermometer while it is still in the water.
- 4: The correct temperature of the bath water will be indicated by the area on the thermometer scale that turns green.

This card is intended for use as a guide only and the manufacturers hold no responsibility for the actions of anyone based on the readings given