

111B



**INSTRUCTIONS FOR USING
BUBBLES BATH THERMOMETER:**

- 1: There are 3 temperature indicators, Cool, Ok, Hot. Start with cool water and gradually add warm until "OK" is green. If no indicator lights, water is too hot or too cold.
- 2: Taking extreme care, thoroughly stir water to avoid potentially hot areas.
- 3: Immerse the bath thermometer completely for 15 seconds, ensuring that the water covers the black oval area of the thermometer. read the temperature of the thermometer while it is still in the water.
- 4: The correct temperature of the bath water will be indicated by the area on the thermometer scale that turns green.

This card is intended for use as a guide only and the manufacturers hold no responsibility for the actions of anyone based on the readings given